10ft SEG Backlit Trade Show
Assembly Instructions

1. Profile Bar w/ LED Stripe (x6)
2. Profile Bar w/ Cable (x2)
3. Profile Bar without Cable (x2)
4. Inner Strut (x7)
5. Base Plate (x2)
6. Bottom Connector (x2)
7. Side Connector (x4)
8. Corner Connector (x2)
9. Middle Cross Connectors (x2)
10. Connecting Cable (x4)
11. Power Supply w/ Device Plugin (x2)
12. Soft Travel Case
13. Graphic

1 Assemble The Frame

Assemble the 3 bottom profile bars w/ LED lights using the bottom connectors an base plates, and connecting cable.

2 Assemble The Frame

Add a Profile Bar with Cable to each side of the display. Also add 2 Inner Struts to the lower half of the assembly.

3 Assemble The Frame

Add Side Connectors, Inner Strut and Middle Cross Bar to complete the horizontal support section.

4 Assemble The Frame

Complete the assembly by adding the remainder of the pieces.

Storage & Care:
Store in a cool dry location. Clean hardware with a damp cloth. Machine wash the graphics in cold water on a gently cycle. Air dry only. Use a steamer for wrinkles. Never dry-clean.

5 **Connect Power Supply**

Connect the power supply to the bottom of the profile bar.

7 **Install The Graphic**

Instal graphics by firmly pushing the silicone edge into the channel on the from of the frame. keep tension on the graphic as you go down each side so that there is enough fabric to reach the end.

Storage & Care:
Store in a cool dry location. Clean hardware with a damp cloth. Machine wash the graphics in cold water on a gently cycle. Air dry only. Use a steamer for wrinkles. Never dry-clean.